

QUALITY ASSURANCE REPORT

PHILIPS Combi Diagnost R90

Item NVI-C00545



QUALITY ASSURANCE INSPECTION | 9 MARCH 2026

MANUFACTURER

Philips

MODALITY

DR / RF

SYSTEM YOM

2023

QA STATUS

PASSED

QA overview

This report records the inspected configuration, component identification, installed software licenses, system condition and available QA test results for the Philips Combi Diagnost R90.

System configuration

System identification, inspection details and detector information

SYSTEM INFORMATION

Manufacturer	Philips	Model	Combi Diagnost R90	Reference	BI335
System model no.	709031	System serial no.	100001204	System YOM	2023-12
Software version	42.3.026	Application	1607.1.10	Inspection date	9 March 2026

DETECTOR INFORMATION

Detector 1 type	Sky Plate Large - Pixium 3543 EZ	Detector 1 YOM	2023
Detector 1 model	63620309	Detector 1 serial	234198
Detector 2 type	PIXIUM 4343RCE - wallstand	Detector 2 YOM	2023
Detector 2 model	63637132A	Detector 2 serial	2346CW
Detector 3 location	Built in table	Detector 3 model	63118113C
Detector 3 serial	233794	Detector 3 size	Not specified

Tube, table and cabinet information

X-ray tubes, patient table, generator and control cabinet

TUBE INFORMATION

Tube 1 model	SRM 0608 ROT-GS 505 - 9890 000 85182	Tube 1 YOM	2023-09
Tube 1 serial	20137C285183	Tube 1 counts	Pending
Tube 2 model	SRO 33100 ROT 380 - 9890 000 86482	Tube 2 YOM	2023-09
Tube 2 serial	69645A285239	Tube 2 counts	Pending

PATIENT TABLE INFORMATION

Table model no.	9890-010-70151	Table serial no.	23102761
Table YOM	2023-10*	Positioning pads	Not included

GENERATOR AND CONTROL CABINET

Generator make / model	100 kW - 9890-000-70307 - Velara GCF 2T	Generator YOM	2023
Generator serial	23004075	Control cabinet model	M-cabinet - 4512-202-03621
Control cabinet serial	373	Control cabinet YOM	Not specified

Data normalization note

*The source document shows the table YOM as "20123-10"; this report presents it as 2023-10 based on the surrounding 2023 system data.

Console and software configuration

Console identification, language and installed software licenses

CONSOLE INFORMATION

Application language	Dutch	Console model no.	4512-202-04321
Console serial no.	KSA6380296	Software version	42.3.026

INSTALLED LICENSES

- CSMotorization
- Dose Reporting
- Reject Analysis
- CollimationWithoutRadiation
- MaxXGenPower 80kW
- SkyFlow
- DICOM Export
- Pulsed Extended Fluoroscopy
- WPD Sharing
- DICOM Print
- RIS MPPS
- Wireless Portable Detector
- DICOM Structured Report
- RIS Worklist Management
- kV Dynamic

SOFTWARE, MANUALS AND ACCESSORIES

Software and manuals	Set available on site	Additional accessories	None listed
----------------------	-----------------------	------------------------	-------------

Condition and QA results

Maintenance status, preparation status and recorded functional tests

2

PASSED

0

FAILED

0

N/A

MAINTENANCE AND CONDITION

System logbook

Not present

Cosmetic condition

Good optical condition

Patient data deletion

Not completed at inspection

Hospital name change

Not completed at inspection

QA TESTING

#	Test performed	Result
1	Movement test	PASSED
2	Test image - 3 repetitions	PASSED

QA conclusion

The two functional tests recorded in the inspection document were completed successfully. Tube counts were still pending at the inspection date.

END OF REPORT